

**DEPARTMENT OF TRANSPORTATION**

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch  
690 Walnut Ave.St. 150  
Vallejo, CA 94592-1133  
(707) 649-5453  
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:**Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-025506**Date Inspected:** 20-Jul-2011**Project Name:** SAS Superstructure**OSM Arrival Time:** 1900**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 700**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Mr. An Qing Xing**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** Orthotropic Box Girder (OBG)**Summary of Items Observed:**

On this day CALTRANS OSM Quality Assurance (QA) Inspector Shailesh Gaikwad was present during the times noted above for observations relative to the fabrication of the SAS Superstructure being performed by Zhenhua Port Machinery Company (ZPMC) at Chang xing Island in Shanghai, China. QA observed and/or found the following:

OBG Trial Assembly

Segment: 13 West

The following Non Destructive Testing (NDT) Inspection was carried out as per the ZPMC submitted Notification No- 9785

**Magnetic Particle Testing (MT)**

This QA randomly witnessed and performed MT of approximately 15% of the area previously tested and accepted by ZPMC Quality Control (QC) personnel. This QA generated a MT report for this date. The members are identified as OBG weld Components. Total number of welds MT tested: (7). The weld designation inspected was as follows:

SEG3013B-251, 252, 253, 254,

SEG3013G-089, 091, 099,

This QA Inspector randomly witnessed MT of the area with AB/F MT Inspector in OBG Segment 13 West. The

---


## WELDING INSPECTION REPORT

( Continued Page 2 of 2 )

---

joint identified as SEG3013G-094 required some welding and grinding and SEG3013G-090 cope hole Profile required correct. This joint has been VT rejected because the weld need repair, For more information see below attached picture number 1.

Unless otherwise noted, all work observed on this date appeared to be in general compliance with the applicable contract documents.



### Summary of Conversations:

Only general conversation was held between QA and QC concerning this project.

### Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang: 15000422372, who represents the Office of Structural Materials for your project.

---

|                      |                  |                             |
|----------------------|------------------|-----------------------------|
| <b>Inspected By:</b> | Gaikwad,Shailesh | Quality Assurance Inspector |
| <b>Reviewed By:</b>  | Patterson,Rodney | QA Reviewer                 |

---